



Systemyde International Corporation
2129 Wedgewood Way
Livermore, CA 94550-6664
(925) 373-0601; FAX (925) 373-0476
e-mail: monted@systemyde.com

41CL B28287 status (01/24/2013)

ITEM 1. Some images aren't listed with CAT 2.

Several images appear not to be listed by CAT 2. They do show up if you halt the CAT and single-step through it. The reason for this is that the CAT function will only list entries with names longer than eight characters. (This was a 41-CX "improvement".) The images in question contain only user-code programs, with names too short to be listed in the main CAT function. The mnemonics known to have this issue are: BSMS (at 0x0CA), ISEN (at 0x0C9), LNDL (at 0x0CD) and TEST (at 0x0CE).

ITEM 2. There is an error in the Image Database.

The entry for the FUNS mnemonic has an error. The address and type fields are correct, so the PLUG functions work correctly, but the two entries with the middle characters of the mnemonic are wrong. These entries should obviously be "UN", but they are actually "AC" in the database.

ITEM 3. One of the images is improperly placed in Flash.

The Advanced Matrix ROM (mnemonic MTRA) is improperly placed in Flash, making it impossible to use. The repair procedure is located at http://www.systemyde.com/pdf/mtra_fix.pdf.